

## No2002                      コンディションチェックシート①

車台番号	NKR88-7004787	点検日	2026/3/18
架装年式	2020年	経過年数	6年
機種	SH12C1RN	号機	800417
点検者	K.O.		
走行距離	21,666km	アワメーター(トータル)	360h
アワメーター(メイン)	345h	アワメーター(サブ)	15h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

### 【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン(バッテリー)/ユニット	異常なし
	ウインチ巻上・巻下	異常なし	アウトリガスライド	-
	緊急停止	異常なし	ジャッキスライド	-
	エンジンスタート・ストップ	異常なし	【備考欄】 異常なし	
下部操作	起伏・伸縮・旋回	異常なし		
	非常用ポンプ	-		
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

株式会社 **アイチ** コーポレーション

## No2002                      コンディションチェックシート②

シャシ年式	2020年	排ガス記号	2RG			
【車両部点検】	車台番号	NKR88-7004787	機種	SH12C1RN	号機	800417
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし			
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	異常なし			
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし			
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし			
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし			
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし			
シート破れ・汚れ	異常なし	首振モーター	異常なし			
内張り破れ・汚れ	異常なし	旋回モーター	異常なし			
ガラス割れ・傷	異常なし	【備考欄】 異常なし				
ミラー割れ・欠品	異常なし					
エアコン作動・能力	異常なし					
ポンプ	異常なし					
タイヤ山	異常なし					

株式会社 **アイチ** コーポレーション

# No2002 Condition Check Sheet 1

Chassis No.	NKR88-7004787		Inspection Date	18 Mar, 2026	
Body Year	2020年		Service Age	6年	
Model	SH12C1RN	S/N	800417	Inspector	K.O.
Mileage	21,666km		Hour Meter (Total)	360h	
Hour Meter (Main)	345h		Hour Meter (Sub)	15h	
Accessories	Included		Operation Manual	Included	

## [Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	Normal
	Winch Up/Down	Normal	Outrigger Slide	-
	Emergency Stop	Normal	Jack Slide	-
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Rotation	Normal	Normal	
	Emergency pump	-		
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



# No2002 Condition Check Sheet 2

Chassis Year	2020年	Emission Standard	2RG		
Chassis No.	NKR88-7004787	Model	SH12C1RN	S/N	800417

## [Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks] Normal	
Mirror Crack/Missing	Normal		
Air Conditioner Operation/Performance	Normal		
Pump	Normal		
Tire Tread Depth	Normal		

