

No2003 コンディションチェックシート①

車台番号	XZU602-0001035	点検日	2026/3/17
架装年式	2017年	経過年数	9年
機種	SH15B	号機	781314
点検者	M.S.		
走行距離	51,285km	アワメーター(トータル)	4,544h
アワメーター(メイン)	820h	アワメーター(サブ)	3,724h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	なし

【架装部点検】


上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/バッテリー/ユニット	異常なし
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回	異常なし	FRPカバー損傷	
	非常用ポンプ	異常なし	バケットライナー割れ	
	緊急停止	異常なし	サブブーム損傷	
	エンジンスタート・ストップ	異常なし		
低騒音エンジン付				

株式会社 **アイチ** コーポレーション

No2003 コンディションチェックシート②

シャシ年式	2017年	排ガス記号	TKG
【車両部点検】	車台番号	XZU602-0001035	機種
			SH15B
			号機
			781314
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	異常なし
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	異常なし	首振モーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】	
ミラー割れ・欠品	異常なし	上部油圧取出しホース油にじみ	
エアコン作動・能力	異常なし		
ポンプ	異常なし		
タイヤ山	異常なし		

株式会社 **アイチ** コーポレーション

No2003		Condition Check Sheet 1			
Chassis No.	XZU602-0001035			Inspection Date	17 Mar, 2026
Body Year	2017年			Service Age	9年
Model	SH15B	S/N	781314	Inspector	M.S.
Mileage	51,285km		Hour Meter (Total)	4,544h	
Hour Meter (Main)	820h		Hour Meter (Sub)	3,724h	
Accessories	Included		Operation Manual	Not Included	
[Body Inspection]					
Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/Unit	Normal	
	Winch Up/Down	Normal	Outrigger Slide	Normal	
	Emergency Stop	Normal	Jack Slide	Normal	
	Engine Start/Stop	Normal	[Remarks]		
Lower Control	Elevation/Extension/Rotation	Normal	FRP Cover Damaged		
	Emergency pump	Normal	Bucket liner crack		
	Emergency Stop	Normal	Sub-Boom Damaged		
	Engine Start/Stop	Normal	Sub-Engine		
					
No2003		Condition Check Sheet 2			
Chassis Year	2017年			Emission Standard	TKG
Chassis No.	XZU602-0001035			Model	SH15B S/N 781314
[Chassis Inspection]					
Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal		
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal		
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal		
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal		
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal		
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal		
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal		
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal		
Glass Crack/Scratch	Normal	[Remarks] upper hydraulic hose Oil Seepage			
Mirror Crack/Missing	Normal				
Air Conditioner Operation/Performance	Normal				
Pump	Normal				
Tire Tread Depth	Normal				
