

## No2006                      コンディションチェックシート①

車台番号	XZU600-0014670	点検日	2026/3/18
架装年式	2017年	経過年数	9年
機種	SH10A	号機	773358
点検者	T.K.		
走行距離	49,378km	アワメーター(トータル)	2,082h
アワメーター(メイン)	2,082h	アワメーター(サブ)	-
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	なし

### 【架装部点検】


上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/バッテリー/ユニット	-
	ウインチ巻上・巻下	-	アウトリガスライド	-
	緊急停止	異常なし	ジャッキスライド	-
	エンジンスタート・ストップ	異常なし	【備考欄】 異常なし	
下部操作	起伏・伸縮・旋回	異常なし		
	非常用ポンプ	異常なし		
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

**株式会社 アイチ コーポレーション**

## No2006                      コンディションチェックシート②

シャシ年式	2017年	排ガス記号	TKG
【車両部点検】	車台番号	XZU600-0014670	機種
			SH10A
			号機
			773358
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	-
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	オイル漏れ有
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	異常なし	首振モーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】 異常なし	
ミラー割れ・欠品	異常なし		
エアコン作動・能力	異常なし		
ポンプ	異常なし		
タイヤ山	異常なし		

**株式会社 アイチ コーポレーション**

No2006		Condition Check Sheet 1			
Chassis No.	XZU600-0014670			Inspection Date	18 Mar, 2026
Body Year	2017年			Service Age	9年
Model	SH10A	S/N	773358	Inspector	T.K.
Mileage	49,378km		Hour Meter (Total)	2,082h	
Hour Meter (Main)	2,082h		Hour Meter (Sub)	-	
Accessories	Included		Operation Manual	Not Included	
<b>[Body Inspection]</b>					
<b>Upper Control</b>	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	-	
	Winch Up/Down	-	Outrigger Slide	-	
	Emergency Stop	Normal	Jack Slide	-	
	Engine Start/Stop	Normal	[Remarks]		
<b>Lower Control</b>	Elevation/Extension/Rotation	Normal	Normal		
	Emergency pump	Normal			
	Emergency Stop	Normal			
	Engine Start/Stop	Normal			
					
No2006		Condition Check Sheet 2			
Chassis Year	2017年			Emission Standard	TKG
Chassis No.	XZU600-0014670			Model	SH10A S/N 773358
<b>[Chassis Inspection]</b>					
Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal		
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	-		
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal		
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal		
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Oil Leak		
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal		
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal		
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal		
Glass Crack/Scratch	Normal	[Remarks] Normal			
Mirror Crack/Missing	Normal				
Air Conditioner Operation/Performance	Normal				
Pump	Normal				
Tire Tread Depth	Normal				
