

## No2009                      コンディションチェックシート①

車台番号	XZU600-0018434	点検日	2026/3/20
架装年式	2018年	経過年数	8年
機種	SH15B	号機	779472
点検者	Y.F.		
走行距離	43,619km	アワメーター(トータル)	4,017h
アワメーター(メイン)	4,230h	アワメーター(サブ)	328h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

### 【架装部点検】


上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン(バッテリー)/ユニット	異常なし
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回	異常なし	アースリールコード損傷	
	非常用ポンプ	-	FRPカバー損傷	
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

株式会社 **アイチ** コーポレーション

## No2009                      コンディションチェックシート②

シャシ年式	2018年	排ガス記号	2KG
【車両部点検】	車台番号	XZU600-0018434	機種      SH15B      号機      779472
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出しシリンダ	異常なし
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デフアレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	異常なし	首振りモーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】 灰皿欠品	
ミラー割れ・欠品	異常なし		
エアコン作動・能力	異常なし		
ポンプ	異常なし		
タイヤ山	異常なし		

株式会社 **アイチ** コーポレーション

No2009		Condition Check Sheet 1			
Chassis No.	XZU600-0018434			Inspection Date	20 Mar, 2026
Body Year	2018年			Service Age	8年
Model	SH15B	S/N	779472	Inspector	Y.F.
Mileage	43,619km		Hour Meter (Total)	4,017h	
Hour Meter (Main)	4,230h		Hour Meter (Sub)	328h	
Accessories	Included		Operation Manual	Included	
<b>[Body Inspection]</b>					
Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	Normal	
	Winch Up/Down	Normal	Outrigger Slide	Normal	
	Emergency Stop	Normal	Jack Slide	Normal	
	Engine Start/Stop	Normal	[Remarks]		
Lower Control	Elevation/Extension/Rotation	Normal	Earth Reel Cord Damaged		
	Emergency pump	-	FRP Cover Damaged		
	Emergency Stop	Normal			
	Engine Start/Stop	Normal			
					
No2009		Condition Check Sheet 2			
Chassis Year	2018年			Emission Standard	2KG
Chassis No.	XZU600-0018434			Model	SH15B
		S/N	779472		
<b>[Chassis Inspection]</b>					
Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal		
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal		
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal		
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal		
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal		
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal		
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal		
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal		
Glass Crack/Scratch	Normal	[Remarks]			
Mirror Crack/Missing	Normal	Ashtray Missing			
Air Conditioner Operation/Performance	Normal				
Pump	Normal				
Tire Tread Depth	Normal				
