

No2011		コンディションチェックシート①			
車台番号	XZU354-0001022		点検日	2026/3/18	
架装年式	2005年		経過年数	21年	
機種	SH15B	号機	685143		点検者
走行距離		151,979km	アワメーター(トータル)	10,466h	
アワメーター(メイン)		213h	アワメーター(サブ)	10,253h	
付属エアコン・スペアタイヤ・車載工具		あり	取扱説明書	なし	
【架装部点検】					
上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン(バッテリー)/ユニット	異常なし	
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし	
	緊急停止	異常なし	ジャッキスライド	異常なし	
	エンジンスタート・ストップ	異常なし	【備考欄】		
下部操作	起伏・伸縮・旋回	異常なし	バケットライナー割れ		
	非常用ポンプ	-	FRPカバー損傷		
	緊急停止	異常なし			
	エンジンスタート・ストップ	異常なし			
株式会社 アイチ コーポレーション					
No2011		コンディションチェックシート②			
シャシ年式	2005年		排ガス記号	PB	
【車両部点検】	車台番号	XZU354-0001022	機種	SH15B	号機
エンジンオイル漏れ・しみ		異常なし	ジャッキシリンダ		異常なし
ラジエーター水漏れ・ホース損傷		異常なし	張出シリンダ		異常なし
セルモーター異音・始動状態		異常なし	起伏シリンダ		異常なし
ミッションオイル漏れ・しみ		異常なし	伸縮シリンダ		異常なし
デファレンシャルオイル漏れ・しみ		異常なし	下部バランスシリンダ		異常なし
マフラ錆・変形		異常なし	上部バランスシリンダ		異常なし
シート破れ・汚れ		異常なし	首振モーター		異常なし
内張り破れ・汚れ		異常なし	旋回モーター		異常なし
ガラス割れ・傷		異常なし	【備考欄】		
ミラー割れ・欠品		異常なし	バッテリーブラケット不良		
エアコン作動・能力		異常なし	シャシフレーム錆・腐食		
ポンプ		異常なし			
タイヤ山		異常なし			
株式会社 アイチ コーポレーション					

No2011 Condition Check Sheet 1

Chassis No.	XZU354-0001022		Inspection Date	18 Mar, 2026	
Body Year	2005年		Service Age	21年	
Model	SH15B	S/N	685143	Inspector	H.T.
Mileage	151,979km		Hour Meter (Total)	10,466h	
Hour Meter (Main)	213h		Hour Meter (Sub)	10,253h	
Accessories	Included		Operation Manual	Not Included	

[Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	Normal
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Rotation	Normal	Bucket liner crack	
	Emergency pump	-	FRP Cover Damaged	
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



No2011 Condition Check Sheet 2

Chassis Year	2005年	Emission Standard	PB		
Chassis No.	XZU354-0001022	Model	SH15B	S/N	685143

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Battery bracket defect	
Air Conditioner Operation/Performance	Normal	Chassis frame rust and corrosion	
Pump	Normal		
Tire Tread Depth	Normal		

