

No2013		コンディションチェックシート①				
車台番号	XZU600-0014706		点検日	2026/3/12		
架装年式	2017年		経過年数	9年		
機種	SH15B	号機	774468		点検者	K.O.
走行距離	37,733km		アワメーター(トータル)	8,221h		
アワメーター(メイン)	661h		アワメーター(サブ)	7,560h		
付属エアコン・スペアタイヤ・車載工具	あり		取扱説明書	あり		
【架装部点検】						
上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/バッテリー/ユニット	異常なし		
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし		
	緊急停止	異常なし	ジャッキスライド	異常なし		
	エンジンスタート・ストップ	異常なし	【備考欄】			
下部操作	起伏・伸縮・旋回	異常なし	ウインチロープ劣化			
	非常用ポンプ	-				
	緊急停止	異常なし				
	エンジンスタート・ストップ	異常なし				
低騒音エンジン付						
株式会社 アイチ コーポレーション						
No2013		コンディションチェックシート②				
シャシ年式	2017年		排ガス記号	TKG		
【車両部点検】	車台番号	XZU600-0014706	機種	SH15B	号機	774468
エンジンオイル漏れ・しみ	異常なし		ジャッキシリンダ	異常なし		
ラジエーター水漏れ・ホース損傷	異常なし		張出シリンダ	異常なし		
セルモーター異音・始動状態	異常なし		起伏シリンダ	にじみ有		
ミッションオイル漏れ・しみ	異常なし		伸縮シリンダ	にじみ有		
デファレンシャルオイル漏れ・しみ	異常なし		下部バランスシリンダ	異常なし		
マフラ錆・変形	異常なし		上部バランスシリンダ	異常なし		
シート破れ・汚れ	異常なし		首振モーター	異常なし		
内張り破れ・汚れ	異常なし		旋回モーター	異常なし		
ガラス割れ・傷	異常なし		【備考欄】			
ミラー割れ・欠品	異常なし		伸縮シリンダオイルにじみ有			
エアコン作動・能力	異常なし		起伏シリンダオイルにじみ有			
ポンプ	異常なし		バケットライナー割れ			
タイヤ山	異常なし		輪止め欠品			
株式会社 アイチ コーポレーション						

No2013

Condition Check Sheet 1

Chassis No.	XZU600-0014706		Inspection Date	12 Mar, 2026	
Body Year	2017年		Service Age	9年	
Model	SH15B	S/N	774468	Inspector	K.O.
Mileage	37,733km		Hour Meter (Total)	8,221h	
Hour Meter (Main)	661h		Hour Meter (Sub)	7,560h	
Accessories	Included		Operation Manual	Included	

[Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	Normal
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Rotation	Normal	Winch rope Deteriorated	
	Emergency pump	-		
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		
			Sub-Engine	



No2013

Condition Check Sheet 2

Chassis Year	2017年	Emission Standard	TKG		
Chassis No.	XZU600-0014706	Model	SH15B	S/N	774468

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Seepage
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Seepage
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Extension Cylinder Oil Seepage	
Air Conditioner Operation/Performance	Normal	Elevation Cylinder Oil Seepage	
Pump	Normal	Bucket liner crack	
Tire Tread Depth	Normal	Wheel Stopper Missing	

