

No2016 **コンディションチェックシート①**

車台番号	XZU600-0048272		点検日	2026/3/17		
架装年式	2024年		経過年数	2年		
機種	D50B1FS	号機	824606		点検者	M.Y.
走行距離	1,973km		アワメーター(トータル)		582h	
搭載品	ジャッキベース	4個	輪止め	4個	取扱説明書	なし
	スペアタイヤ	あり	車載工具	あり		

【架装部点検】


作動確認	起伏・伸縮・旋回	異常なし	アタッチメント・ツール	異常なし
	ウインチ巻上・巻下	異常なし	ドライブシャフト	異常なし
	オーガ装置	異常なし	【備考欄】	
	過巻装置	異常なし	モーメントリミッター(安全装置付)	
	アウトリガ・ジャッキ	異常なし		
	エンジンスタート・ストップ	異常なし		
	作業灯	異常なし		
	ホーン	異常なし		

株式会社 アイチ コーポレーション

No2016 **コンディションチェックシート②**

シャシ年式	2024年		排ガス記号	2KG		
【車両部点検】	車台番号	XZU600-0048272	機種	D50B1FS	号機	824606
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ		異常なし		
ラジエーター水漏れ・ホース損傷	異常なし	張出しシリンダ		異常なし		
セルモーター異音・始動状態	異常なし	起伏シリンダ		異常なし		
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ		異常なし		
デファレンシャルオイル漏れ・しみ	異常なし	オーガ減速機		異常なし		
マフラ錆・変形	異常なし	旋回減速機		異常なし		
シート破れ・汚れ	異常なし	ウインチ減速機		異常なし		
内張り破れ・汚れ	異常なし	ウインチワイヤー		異常なし		
ガラス割れ・傷	異常なし	オーガー格納ワイヤー		異常なし		
ミラー割れ・欠品	異常なし	【備考欄】				
エアコン作動・能力	異常なし	フック格納BKT損傷				
ポンプ	異常なし					
タイヤ山	異常なし					

株式会社 アイチ コーポレーション

No2016 Condition Check Sheet 1								
Chassis No.		XZU600-0048272			Inspection Date		17 Mar, 2026	
Body Year		2024年			Service Age		2年	
Model	D50B1FS	S/N	824606		Inspector		M.Y.	
Mileage		1,973km		Hour Meter (Total)		582h		
Accessories		Jack Bases	4pc	Wheel Stoppers	4pc	Operation Manual	Not Included	
		Spare Tires	Included	On-board Tools	Included			
[Body Inspection]								
Control	Elevation/Extension/Rotation		Normal	Attachment/Tool		Normal		
	Winch Up/Down		Normal	Drive Shaft		Normal		
	Auger		Normal	[Remarks]				
	Over-Hoist Limit Device		Normal	With moment limiter (With safety device)				
	Outrigger/Jack		Normal					
	Engine Start/Stop		Normal					
	Work Light		Normal					
	Horn		Normal					
								

No2016 Condition Check Sheet 2							
Chassis Year		2024年			Emission Standard		2KG
Chassis No.		XZU600-0048272			Model	D50B1FS	S/N 824606
[Chassis Inspection]							
Engine Oil Leak/Seepage		Normal	Jack Cylinder		Normal		
Radiator Water Leak/Hose Damage		Normal	Outrigger Cylinder		Normal		
Starter Motor Noise/Starting Condition		Normal	Elevation Cylinder		Normal		
Transmission Oil Leak/Seepage		Normal	Telescopic Cylinder		Normal		
Differential Oil Leak/Seepage		Normal	Auger Reduction Gear		Normal		
Muffler Rust/Deformation		Normal	Rotation Reduction Gear		Normal		
Seat Tear/Stain		Normal	Winch Reduction Gear		Normal		
Interior Panel Tear/Stain		Normal	Winch Wire		Normal		
Glass Crack/Scratch		Normal	Auger Stowage Wire		Normal		
Mirror Crack/Missing		Normal	[Remarks]				
Air Conditioner Operation/Performance		Normal	Hook storage BKT damage				
Pump		Normal					
Tire Tread Depth		Normal					
