


No2018		Condition Check Sheet 1			
Chassis No.	FC9JGA-11500			Inspection Date	05 Mar, 2026
Body Year	2016年			Service Age	10年
Model	D70A	S/N	768187	Inspector	S.I
Mileage	55,085km		Hour Meter (Total)	2,568h	
Accessories	Jack Bases	4pc	Wheel Stoppers	4pc	Operation Manual
	Spare Tires	Included	On-board Tools	Included	Included
[Body Inspection]					
Control	Elevation/Extension/Rotation	Normal	Attachment/Tool	Worn	
	Winch Up/Down	Normal	Drive Shaft	Normal	
	Auger	Deformation	[Remarks]		
	Over-Hoist Limit Device	Normal	Auger Blade Deformation		
	Outrigger/Jack	Normal	Overwind wire Damaged		
	Engine Start/Stop	Normal	AugerHead Cutter bit Wear		
	Work Light	Normal	Tool Box deformation		
	Horn	Normal			
					

No2018		Condition Check Sheet 2			
Chassis Year	2016年		Emission Standard	TKG	
	Chassis No.	FC9JGA-11500	Model	D70A	S/N 768187
[Chassis Inspection]					
Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal		
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal		
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal		
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal		
Differential Oil Leak/Seepage	Normal	Auger Reduction Gear	Normal		
Muffler Rust/Deformation	Normal	Rotation Reduction Gear	Normal		
Seat Tear/Stain	Normal	Winch Reduction Gear	Normal		
Interior Panel Tear/Stain	Stained	Winch Wire	Rust		
Glass Crack/Scratch	Normal	Auger Stowage Wire	Rust		
Mirror Crack/Missing	Normal	[Remarks]			
Air Conditioner Operation/Performance	Normal	Exterior Corrosion			
Pump	Normal	Rear bumper deformation			
Tire Tread Depth	Normal	Stained (Driver Seat)			
