

コンディションチェックシート①

車台番号	FE53EB-565118	点検日	2026/2/28
架装年式	2002年	経過年数	24年
機種	SS12A	号機	674117
走行距離	139,269km	点検者	N.K.
アワメーター(メイン)	9,923h	アワメーター(サブ)	-
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	なし

【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異常なし	バッテリーユニット	-
	ウインチ巻上・巻下	-	アウトリガスライド	-
	緊急停止	異常なし	ジャッキスライド	-
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回・首振り	異常なし	メーターパネルPTOランプ不灯	
			シフトレバーガタ有	
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

株式会社 **アイチ** コーポレーション

コンディションチェックシート②

シャシ年式	2016年	排ガス記号	KK
【車両部点検】	車台番号	FE53EB-565118	機種
			SS12A
			号機
			674117
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	-
セルモーター異音・始動状態	異常なし	起伏シリンダ	オイルにじみ有
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	オイルにじみ有
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	オイル漏れ有
マフラ錆・変形	錆有	上部バランスシリンダ	異常なし
シート破れ・汚れ	異常なし	首振モーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】	
ミラー割れ・欠品	ミラー損傷有	起伏シリンダオイルにじみ有	
エアコン作動・能力	異常なし	伸縮シリンダオイルにじみ有	
ポンプ	異常なし	下部レベリングシリンダ油漏れ	
タイヤ山	タイヤ摩耗有	ミラー損傷有	
		タイヤ摩耗有	

株式会社 **アイチ** コーポレーション

Condition Check Sheet 1

Chassis No.	FE53EB-565118	Inspection Date	28 Feb, 2026
Body Year	2002年	Service Age	24年
Model	SS12A	S/N	674117
Mileage	139,269km	Hour Meter (Total)	9,923h
Hour Meter (Main)	9,923h	Hour Meter (Sub)	-
Accessories	Included	Operation Manual	Not Included

[Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Battery Unit	-
	Winch Up/Down	-	Outrigger Slide	-
	Emergency Stop	Normal	Jack Slide	-
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Meter panel PTO lamp not lit The shift lever has play	
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



Condition Check Sheet 2

Chassis Year	2016年	Emission Standard	KK
	Chassis No. FE53EB-565118	Model	SS12A
		S/N	674117

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	-
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Oil Seepage
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Oil Seepage
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Oil Leak
Muffler Rust/Deformation	Rust	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Mirror damaged	Elevation Cylinder Oil Seepage	
Air Conditioner Operation/Performance	Normal	Extension Cylinder Oil Seepage	
Pump	Normal	Lower Leveling cylinder oil leak	
Tire Tread Depth	Tire Wear	Mirror damaged	
		Tire Wear	

