

コンディションチェックシート①

| | | | |
|--------------------|-----------------|------------|-----------|
| 車台番号 | XZU600X-0015677 | 点検日 | 2026/2/28 |
| 架装年式 | 2017年 | 経過年数 | 9年 |
| 機種 | SH11A | 号機 | 776074 |
| 走行距離 | 59,304km | 点検者 | K.Y. |
| アワメーター(メイン) | 2,824h | アワメーター(サブ) | 1,913h |
| 付属エアコン・スペアタイヤ・車載工具 | あり | 取扱説明書 | あり |

【架装部点検】

| | | | | |
|------|---------------|------|-------------------|------|
| 上部操作 | 起伏・伸縮・旋回・首振り | 異常なし | (エンジン) バッテリー/ユニット | 異常なし |
| | ウインチ巻上・巻下 | - | アウトリガスライド | - |
| | 緊急停止 | 異常なし | ジャッキスライド | - |
| | エンジンスタート・ストップ | 異常なし | 【備考欄】 | |
| 下部操作 | 起伏・伸縮・旋回・首振り | 異常なし | 異常なし | |
| | 緊急停止 | 異常なし | | |
| | エンジンスタート・ストップ | 異常なし | | |

株式会社 アイチ コーポレーション

コンディションチェックシート②

| | | | |
|------------------|--------|-----------------|--------|
| シャシ年式 | 2017年 | 排ガス記号 | TKG |
| 【車両部点検】 | 車台番号 | XZU600X-0015677 | 機種 |
| | | | SH11A |
| | | | 号機 |
| | | | 776074 |
| エンジンオイル漏れ・しみ | 異常なし | ジャッキシリンダ | 異常なし |
| ラジエーター水漏れ・ホース損傷 | 異常なし | 張出シリンダ | - |
| セルモーター異音・始動状態 | 異常なし | 起伏シリンダ | 異常なし |
| ミッションオイル漏れ・しみ | 異常なし | 伸縮シリンダ | 異常なし |
| デファレンシャルオイル漏れ・しみ | 異常なし | 下部バランスシリンダ | 異常なし |
| マフラ錆・変形 | 異常なし | 上部バランスシリンダ | 異常なし |
| シート破れ・汚れ | 異常なし | 首振モーター | 異常なし |
| 内張り破れ・汚れ | 異常なし | 旋回モーター | 異常なし |
| ガラス割れ・傷 | 異常なし | 【備考欄】 | |
| ミラー割れ・欠品 | 異常なし | タイヤ摩耗有 | |
| エアコン作動・能力 | 異常なし | | |
| ポンプ | 異常なし | | |
| タイヤ山 | タイヤ摩耗有 | | |

株式会社 アイチ コーポレーション

Condition Check Sheet 1

| | | | |
|-------------------|-----------------|--------------------|--------------|
| Chassis No. | XZU600X-0015677 | Inspection Date | 28 Feb, 2026 |
| Body Year | 2017年 | Service Age | 9年 |
| Model | SH11A | S/N | 776074 |
| Mileage | 59,304km | Hour Meter (Total) | 4,837h |
| Hour Meter (Main) | 2,824h | Hour Meter (Sub) | 1,913h |
| Accessories | Included | Operation Manual | Included |

[Body Inspection]

| | | | | |
|----------------------|---|--------|------------------------|--------|
| Upper Control | Elevation/Extension/Retraction/Rotation/Swing | Normal | (Engine) Battery/ Unit | Normal |
| | Winch Up/Down | - | Outtrigger Slide | - |
| | Emergency Stop | Normal | Jack Slide | - |
| | Engine Start/Stop | Normal | [Remarks] | |
| Lower Control | Elevation/Extension/Retraction/Rotation/Swing | Normal | Normal | |
| | Emergency Stop | Normal | | |
| | Engine Start/Stop | Normal | | |



Condition Check Sheet 2

| | | | |
|--------------|-----------------------------|-------------------|--------|
| Chassis Year | 2017年 | Emission Standard | TKG |
| | Chassis No. XZU600X-0015677 | Model | SH11A |
| | | S/N | 776074 |

[Chassis Inspection]

| | | | |
|--|-----------|--------------------------|--------|
| Engine Oil Leak/Seepage | Normal | Jack Cylinder | Normal |
| Radiator Water Leak/Hose Damage | Normal | Outtrigger Cylinder | - |
| Starter Motor Noise/Starting Condition | Normal | Elevation Cylinder | Normal |
| Transmission Oil Leak/Seepage | Normal | Telescopic Cylinder | Normal |
| Differential Oil Leak/Seepage | Normal | Balance Cylinder (Lower) | Normal |
| Muffler Rust/Deformation | Normal | Balance Cylinder (Upper) | Normal |
| Seat Tear/Stain | Normal | Bucket Swing Motor | Normal |
| Interior Panel Tear/Stain | Normal | Rotation Motor | Normal |
| Glass Crack/Scratch | Normal | [Remarks] | |
| Mirror Crack/Missing | Normal | Tire Wear | |
| Air Conditioner Operation/Performance | Normal | | |
| Pump | Normal | | |
| Tire Tread Depth | Tire Wear | | |

