

No2001		コンディションチェックシート①				
車台番号	XZU600-0018148			点検日	2026/3/19	
架装年式	2017年			経過年数	9年	
機種	SH15B	号機	781319		点検者	H.T.
走行距離	6,568km		アワメーター(トータル)	1,702h		
アワメーター(メイン)	1,699h		アワメーター(サブ)	3h		
付属エアコン・スペアタイヤ・車載工具	あり		取扱説明書	なし		
<b>【架装部点検】</b>						
上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン(バッテリー)/ユニット	異常なし		
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし		
	緊急停止	異常なし	ジャッキスライド	異常なし		
	エンジンスタート・ストップ	異常なし	【備考欄】			
下部操作	起伏・伸縮・旋回	異常なし	異常なし			
	非常用ポンプ	-				
	緊急停止	異常なし				
	エンジンスタート・ストップ	異常なし				
株式会社 アイチ コーポレーション						
No2001		コンディションチェックシート②				
シャシ年式	2017年			排ガス記号	2KG	
<b>【車両部点検】</b>	車台番号	XZU600-0018148	機種	SH15B	号機	781319
エンジンオイル漏れ・しみ	異常なし		ジャッキシリンダ	異常なし		
ラジエーター水漏れ・ホース損傷	異常なし		張出シリンダ	異常なし		
セルモーター異音・始動状態	異常なし		起伏シリンダ	異常なし		
ミッションオイル漏れ・しみ	異常なし		伸縮シリンダ	異常なし		
デファレンシャルオイル漏れ・しみ	異常なし		下部バランスシリンダ	異常なし		
マフラ錆・変形	異常なし		上部バランスシリンダ	異常なし		
シート破れ・汚れ	異常なし		首振モーター	異常なし		
内張り破れ・汚れ	異常なし		旋回モーター	異常なし		
ガラス割れ・傷	異常なし		【備考欄】			
ミラー割れ・欠品	異常なし		異常なし			
エアコン作動・能力	異常なし					
ポンプ	異常なし					
タイヤ山	異常なし					
株式会社 アイチ コーポレーション						

# No2001 Condition Check Sheet 1

Chassis No.	XZU600-0018148		Inspection Date	19 Mar, 2026	
Body Year	2017年		Service Age	9年	
Model	SH15B	S/N	781319	Inspector	H.T.
Mileage	6,568km		Hour Meter (Total)	1,702h	
Hour Meter (Main)	1,699h		Hour Meter (Sub)	3h	
Accessories	Included		Operation Manual	Not Included	

## [Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/ <del>Battery</del> / Unit	Normal
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Rotation	Normal	Normal	
	Emergency pump	-		
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



# No2001 Condition Check Sheet 2

Chassis Year	2017年	Emission Standard	2KG		
Chassis No.	XZU600-0018148	Model	SH15B	S/N	781319

## [Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks] Normal	
Mirror Crack/Missing	Normal		
Air Conditioner Operation/Performance	Normal		
Pump	Normal		
Tire Tread Depth	Normal		

