No2001　　コンディションチェックシート①

車台番号		FC6JGWA-10553		点検日	2026/6/9
架装年式		2008年		経過年数	18年
機種	SK27A	号機	715911	点検者	Y.S
走行距離		195,510km		アワメーター（トータル）	8,633h
アワメーター（メイン）		8,633h		アワメーター（サブ）	0h
付属エアコン・スペアタイヤ・車載工具		車載工具なし		取扱説明書	あり

【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/バッテリー/ユニット	－
	ウインチ巻上・巻下	－	アウトリガスライド	異常なし
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回	異常なし		
	非常用ポンプ	異常なし		
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

株式会社アイチコーポレーション

No2001　　コンディションチェックシート②

シャシ年式	2008年		排ガス記号		BDG		
【車両部点検】	車台番号	FC6JGWA-10553	機種	SK27A	号機	715911	
エンジンオイル漏れ・しみ	異常なし		ジャッキシリンダ		異常なし		
ラジエーター水漏れ・ホース損傷	異常なし		張出シリンダ		異常なし		
セルモーター異音・始動状態	異常なし		起伏シリンダ		異常なし		
ミッションオイル漏れ・しみ	異常なし		伸縮シリンダ		異常なし		
デファレンシャルオイル漏れ・しみ	異常なし		下部バランスシリンダ		異常なし		
マフラ錆・変形	異常なし		上部バランスシリンダ		異常なし		
シート破れ・汚れ	破れ有		首振モーター		異常なし		
内張り破れ・汚れ	異常なし		旋回モーター		異常なし		
ガラス割れ・傷	異常なし		【備考欄】 作動油タンクオイルにじみ有 運転席破れ有				
ミラー割れ・欠品	異常なし						
エアコン作動・能力	異常なし						
ポンプ	異常なし						
タイヤ山	異常なし						

株式会社アイチコーポレーション

No2001 Condition Check Sheet 1

Chassis No.		FC6JGWA-10553		Inspection Date	09 Jun, 2026
Body Year		2008年		Service Age	18年
Model	SK27A	S/N	715911	Inspector	Y.S
Mileage		195,510km		Hour Meter (Total)	8,633h
Hour Meter (Main)		8,633h		Hour Meter (Sub)	0h
Accessories		No onboard tools		Operation Manual	Included

[Body Inspection]

Upper Control	Elevation/Extension/ Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	-
	Winch Up/Down	-	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Rotation	Normal		
	Emergency pump	Normal		
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		

ICHI CORPORATION

No2001 Condition Check Sheet 2

Chassis Year	2008年	Emission Standard		BDG	
Chassis No.	FC6JGWA-10553	Model	SK27A	S/N	715911

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Torn	Backet Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Hydraulic oil tank oil Seepage	
Air Conditioner Operation/Performance	Normal	Torn (Driver Seat)	
Pump	Normal		
Tire Tread Depth	Normal		

ICHI CORPORATION