


No2004		コンディションチェックシート①			
車台番号	XZU600-0009925		点検日	2026/3/11	
架装年式	2015年		経過年数	11年	
機種	SH10A	号機	757613	点検者	Y.S.
走行距離	14,672km		アワメーター(トータル)	1,254h	
アワメーター(メイン)	1,239h		アワメーター(サブ)	15h	
付属エアコン・スペアタイヤ・車載工具	あり		取扱説明書	あり	
【架装部点検】					
上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/ バッテリー /ユニット	異常なし	
	ウインチ巻上・巻下	-	アウトリガスライド	-	
	緊急停止	異常なし	ジャッキスライド	-	
	エンジンスタート・ストップ	異常なし	【備考欄】		
下部操作	起伏・伸縮・旋回	異常なし	簡易バッテリー駆動型(PD100)		
	非常用ポンプ	-			
	緊急停止	異常なし			
	エンジンスタート・ストップ	異常なし			
株式会社 アイチ コーポレーション					
No2004		コンディションチェックシート②			
シャシ年式	2015年		排ガス記号	TKG	
【車両部点検】	車台番号	XZU600-0009925	機種	SH10A	号機 757613
エンジンオイル漏れ・しみ	異常なし		ジャッキシリンダ	異常なし	
ラジエーター水漏れ・ホース損傷	異常なし		張出シリンダ	異常なし	
セルモーター異音・始動状態	異常なし		起伏シリンダ	異常なし	
ミッションオイル漏れ・しみ	異常なし		伸縮シリンダ	異常なし	
デファレンシャルオイル漏れ・しみ	異常なし		下部バランスシリンダ	異常なし	
マフラ錆・変形	異常なし		上部バランスシリンダ	異常なし	
シート破れ・汚れ	異常なし		首振モーター	異常なし	
内張り破れ・汚れ	異常なし		旋回モーター	異常なし	
ガラス割れ・傷	異常なし		【備考欄】		
ミラー割れ・欠品	異常なし		異常なし		
エアコン作動・能力	異常なし				
ポンプ	異常なし				
タイヤ山	異常なし				
株式会社 アイチ コーポレーション					

No2004		Condition Check Sheet 1			
Chassis No.	XZU600-0009925			Inspection Date	11 Mar, 2026
Body Year	2015年			Service Age	11年
Model	SH10A	S/N	757613	Inspector	Y.S.
Mileage	14,672km		Hour Meter (Total)	1,254h	
Hour Meter (Main)	1,239h		Hour Meter (Sub)	15h	
Accessories	Included		Operation Manual	Included	
[Body Inspection]					
Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/ Battery / Unit	Normal	
	Winch Up/Down	-	Outrigger Slide	-	
	Emergency Stop	Normal	Jack Slide	-	
	Engine Start/Stop	Normal	[Remarks]		
Lower Control	Elevation/Extension/Rotation	Normal	Easy battery-powered(PD100)		
	Emergency pump	-			
	Emergency Stop	Normal			
	Engine Start/Stop	Normal			
					
No2004		Condition Check Sheet 2			
Chassis Year	2015年			Emission Standard	TKG
Chassis No.	XZU600-0009925		Model	SH10A	S/N 757613
[Chassis Inspection]					
Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal		
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal		
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal		
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal		
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal		
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal		
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal		
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal		
Glass Crack/Scratch	Normal	[Remarks]			
Mirror Crack/Missing	Normal	Normal			
Air Conditioner Operation/Performance	Normal				
Pump	Normal				
Tire Tread Depth	Normal				
