

No2005		コンディションチェックシート①				
車台番号	XZU600-0010032		点検日	2026/3/13		
架装年式	2015年		経過年数	11年		
機種	SH15B	号機	757709		点検者	K.O.
走行距離	70,857km		アワメーター(トータル)	8,706h		
アワメーター(メイン)	1,830h		アワメーター(サブ)	6,876h		
付属エアコン・スペアタイヤ・車載工具	あり		取扱説明書	あり		
<b>【架装部点検】</b>						
上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/バッテリー/ユニット	異常なし		
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし		
	緊急停止	異常なし	ジャッキスライド	異常なし		
	エンジンスタート・ストップ	異常なし	【備考欄】			
下部操作	起伏・伸縮・旋回	異常なし	FRPカバー損傷	上部油圧取出しホーススキズ  低騒音エンジン付		
	非常用ポンプ	-	上部油圧取出しホーススキズ			
	緊急停止	異常なし				
	エンジンスタート・ストップ	異常なし				
<b>株式会社 アイチ コーポレーション</b>						
No2005		コンディションチェックシート②				
シャシ年式	2015年		排ガス記号	TKG		
<b>【車両部点検】</b>	車台番号	XZU600-0010032	機種	SH15B	号機	757709
エンジンオイル漏れ・しみ	異常なし		ジャッキシリンダ	異常なし		
ラジエーター水漏れ・ホース損傷	異常なし		張出しシリンダ	異常なし		
セルモーター異音・始動状態	異常なし		起伏シリンダ	異常なし		
ミッションオイル漏れ・しみ	異常なし		伸縮シリンダ	にじみ有		
デフアレンシャルオイル漏れ・しみ	異常なし		下部バランスシリンダ	異常なし		
マフラ錆・変形	異常なし		上部バランスシリンダ	異常なし		
シート破れ・汚れ	破れ有		首振モーター	異常なし		
内張り破れ・汚れ	異常なし		旋回モーター	異常なし		
ガラス割れ・傷	異常なし		【備考欄】			
ミラー割れ・欠品	異常なし		伸縮シリンダオイルにじみ有			
エアコン作動・能力	異常なし		運転席破れ有			
ポンプ	異常なし					
タイヤ山	異常なし					
<b>株式会社 アイチ コーポレーション</b>						

# No2005 Condition Check Sheet 1

Chassis No.	XZU600-0010032		Inspection Date	13 Mar, 2026	
Body Year	2015年		Service Age	11年	
Model	SH15B	S/N	757709	Inspector	K.O.
Mileage	70,857km		Hour Meter (Total)	8,706h	
Hour Meter (Main)	1,830h		Hour Meter (Sub)	6,876h	
Accessories	Included		Operation Manual	Included	

## [Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	Normal
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Rotation	Normal	FRP Cover Damaged	
	Emergency pump	-	upper hydraulic outlet hose	
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		
			Sub-Engine	



# No2005 Condition Check Sheet 2

Chassis Year	2015年	Emission Standard	TKG		
Chassis No.	XZU600-0010032	Model	SH15B	S/N	757709

## [Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Seepage
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Torn	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Extension Cylinder Oil Seepage	
Air Conditioner Operation/Performance	Normal	Torn (Driver Seat)	
Pump	Normal		
Tire Tread Depth	Normal		

