


No2007		コンディションチェックシート①				
車台番号	XZU600-0009797			点検日	2026/3/11	
架装年式	2015年			経過年数	11年	
機種	SH15B	号機	756961		点検者	Y.S.
走行距離	18,452km		アワメーター(トータル)	3,263h		
アワメーター(メイン)	3,081h		アワメーター(サブ)	182h		
付属エアコン・スペアタイヤ・車載工具	あり		取扱説明書	あり		
【架装部点検】						
上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン(バッテリー)/ユニット	異常なし		
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし		
	緊急停止	異常なし	ジャッキスライド	異常なし		
	エンジンスタート・ストップ	異常なし	【備考欄】			
下部操作	起伏・伸縮・旋回	異常なし	異常なし			
	非常用ポンプ	-				
	緊急停止	異常なし				
	エンジンスタート・ストップ	異常なし				
株式会社 アイチ コーポレーション						
No2007		コンディションチェックシート②				
シャシ年式	2015年		排ガス記号	TKG		
【車両部点検】	車台番号	XZU600-0009797	機種	SH15B	号機	756961
エンジンオイル漏れ・しみ	異常なし		ジャッキシリンダ	異常なし		
ラジエーター水漏れ・ホース損傷	異常なし		張出しシリンダ	異常なし		
セルモーター異音・始動状態	異常なし		起伏シリンダ	異常なし		
ミッションオイル漏れ・しみ	異常なし		伸縮シリンダ	異常なし		
デフレンシャルオイル漏れ・しみ	異常なし		下部バランスシリンダ	異常なし		
マフラ錆・変形	異常なし		上部バランスシリンダ	異常なし		
シート破れ・汚れ	異常なし		首振モーター	異常なし		
内張り破れ・汚れ	異常なし		旋回モーター	異常なし		
ガラス割れ・傷	異常なし		【備考欄】			
ミラー割れ・欠品	異常なし		スペアタイヤ損傷			
エアコン作動・能力	異常なし					
ポンプ	異常なし					
タイヤ山	異常なし					
株式会社 アイチ コーポレーション						

No2007		Condition Check Sheet 1					
Chassis No.		XZU600-0009797		Inspection Date		11 Mar, 2026	
Body Year		2015年		Service Age		11年	
Model	SH15B	S/N	756961		Inspector		Y.S.
Mileage		18,452km		Hour Meter (Total)		3,263h	
Hour Meter (Main)		3,081h		Hour Meter (Sub)		182h	
Accessories		Included		Operation Manual		Included	
[Body Inspection]							
Upper Control	Elevation/Extension/Retraction/Rotation/Swing		Normal	Engine/Battery/ Unit		Normal	
	Winch Up/Down		Normal	Outrigger Slide		Normal	
	Emergency Stop		Normal	Jack Slide		Normal	
	Engine Start/Stop		Normal	[Remarks]			
Lower Control	Elevation/Extension/Rotation		Normal	Normal			
	Emergency pump		-				
	Emergency Stop		Normal				
	Engine Start/Stop		Normal				
							
No2007		Condition Check Sheet 2					
Chassis Year		2015年		Emission Standard		TKG	
Chassis No.		XZU600-0009797		Model	SH15B	S/N	756961
[Chassis Inspection]							
Engine Oil Leak/Seepage		Normal		Jack Cylinder		Normal	
Radiator Water Leak/Hose Damage		Normal		Outrigger Cylinder		Normal	
Starter Motor Noise/Starting Condition		Normal		Elevation Cylinder		Normal	
Transmission Oil Leak/Seepage		Normal		Telescopic Cylinder		Normal	
Differential Oil Leak/Seepage		Normal		Balance Cylinder (Lower)		Normal	
Muffler Rust/Deformation		Normal		Balance Cylinder (Upper)		Normal	
Seat Tear/Stain		Normal		Bucket Swing Motor		Normal	
Interior Panel Tear/Stain		Normal		Rotation Motor		Normal	
Glass Crack/Scratch		Normal		[Remarks] Spare tire damaged			
Mirror Crack/Missing		Normal					
Air Conditioner Operation/Performance		Normal					
Pump		Normal					
Tire Tread Depth		Normal					
