

No2008		コンディションチェックシート①			
車台番号	XZU354-1000020			点検日	2026/3/11
架装年式	2005年			経過年数	21年
機種	SN15B	号機	693076	点検者	Y.S.
走行距離	122,797km			アワメーター(トータル)	5,498h
アワメーター(メイン)	1,394h			アワメーター(サブ)	4,104h
付属エアコン・スペアタイヤ・車載工具	あり			取扱説明書	なし
<b>【架装部点検】</b>					
上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/バッテリー/ユニット	異常なし	
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし	
	緊急停止	異常なし	ジャッキスライド	異常なし	
	エンジンスタート・ストップ	異常なし	【備考欄】		
下部操作	起伏・伸縮・旋回	異常なし	サブブームシーブ割れ		
	非常用ポンプ	-	バケットライナー割れ		
	緊急停止	異常なし	FRPカバー損傷		
	エンジンスタート・ストップ	異常なし	低騒音エンジン付		
株式会社 アイチ コーポレーション					
No2008		コンディションチェックシート②			
シャシ年式	2005年			排ガス記号	PB
<b>【車両部点検】</b>	車台番号	XZU354-1000020	機種	SN15B	号機 693076
エンジンオイル漏れ・しみ	オイルにじみ有		ジャッキシリンダ		異常なし
ラジエーター水漏れ・ホース損傷	漏れ有		張出シリンダ		異常なし
セルモーター異音・始動状態	漏れ有		起伏シリンダ		異常なし
ミッションオイル漏れ・しみ	異常なし		伸縮シリンダ		異常なし
デファレンシャルオイル漏れ・しみ	異常なし		下部バランスシリンダ		異常なし
マフラ錆・変形	錆有		上部バランスシリンダ		異常なし
シート破れ・汚れ	破れ有		首振モーター		異常なし
内張り破れ・汚れ	異常なし		旋回モーター		異常なし
ガラス割れ・傷	異常なし		【備考欄】		
ミラー割れ・欠品	カバー割れ		工具箱腐食有		
エアコン作動・能力	異常なし		エンジンオイルにじみ		
ポンプ	異常なし		ラジエーター水漏れ		
タイヤ山	異常なし		シート破れ・汚れ有		
株式会社 アイチ コーポレーション					

# No2008 Condition Check Sheet 1

Chassis No.	XZU354-1000020			Inspection Date	11 Mar, 2026
Body Year	2005年			Service Age	21年
Model	SN15B	S/N	693076	Inspector	Y.S.
Mileage	122,797km		Hour Meter (Total)	5,498h	
Hour Meter (Main)	1,394h		Hour Meter (Sub)	4,104h	
Accessories	Included		Operation Manual	Not Included	

## [Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine Battery/ Unit	Normal
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Rotation	Normal	Sub-Boom Sheave Cracked	
	Emergency pump	-	Bucket liner crack	
	Emergency Stop	Normal	FRP Cover Damaged	
	Engine Start/Stop	Normal		
			Sub-Engine	



# No2008 Condition Check Sheet 2

Chassis Year	2005年			Emission Standard	PB
Chassis No.	XZU354-1000020			Model	SN15B S/N 693076

## [Chassis Inspection]

Engine Oil Leak/Seepage	Oil Seepage	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Leak	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Leak	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Rust	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Torn	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Cover Cracked	Tool Box Corroded	
Air Conditioner Operation/Performance	Normal	Engine Oil Seepage	
Pump	Normal	Radiator water leak	
Tire Tread Depth	Normal	Sheet Stained & Torn	

