

No2010						コンディションチェックシート①					
車台番号		XZU354-1002962				点検日		2026/3/16			
架装年式		2011年				経過年数		15年			
機種	SN15B	号機	733416			点検者		H.K.			
走行距離		164,518km			アワメーター(トータル)		15,750h				
アワメーター(メイン)			1,814h		アワメーター(サブ)		13,936h				
付属エアコン・スペアタイヤ・車載工具			あり		取扱説明書		あり				
【架装部点検】											
上部操作	起伏・伸縮・旋回・首振り		異常なし		エンジン/バッテリー/ユニット		異常なし				
	ウインチ巻上・巻下		異常なし		アウトリガスライド		異常なし				
	緊急停止		異常なし		ジャッキスライド		異常なし				
	エンジンスタート・ストップ		異常なし		【備考欄】						
下部操作	起伏・伸縮・旋回		異常なし		工具箱腐食有						
	非常用ポンプ		-		上部操作LED破損有						
	緊急停止		異常なし		FRPカバー損傷						
	エンジンスタート・ストップ		異常なし		低騒音エンジン付						
株式会社 アイチ コーポレーション											
No2010						コンディションチェックシート②					
シャシ年式		2011年				排ガス記号		BDG			
【車両部点検】		車台番号	XZU354-1002962		機種	SN15B	号機	733416			
エンジンオイル漏れ・しみ		オイルにじみ有		ジャッキシリンダ		異常なし					
ラジエーター水漏れ・ホース損傷		異常なし		張出しシリンダ		異常なし					
セルモーター異音・始動状態		異常なし		起伏シリンダ		異常なし					
ミッションオイル漏れ・しみ		異常なし		伸縮シリンダ		異常なし					
デファレンシャルオイル漏れ・しみ		異常なし		下部バランスシリンダ		異常なし					
マフラ錆・変形		異常なし		上部バランスシリンダ		異常なし					
シート破れ・汚れ		異常なし		首振りモーター		異常なし					
内張り破れ・汚れ		汚れ有		旋回モーター		異常なし					
ガラス割れ・傷		異常なし		【備考欄】							
ミラー割れ・欠品		異常なし		エンジン本体上部に燃料にじみ有							
エアコン作動・能力		異常なし		キャビン内汚れ有							
ポンプ		異常なし									
タイヤ山		異常なし									
株式会社 アイチ コーポレーション											

# No2010 Condition Check Sheet 1

Chassis No.	XZU354-1002962			Inspection Date	16 Mar, 2026
Body Year	2011年			Service Age	15年
Model	SN15B	S/N	733416	Inspector	H.K.
Mileage	164,518km		Hour Meter (Total)	15,750h	
Hour Meter (Main)	1,814h		Hour Meter (Sub)	13,936h	
Accessories	Included		Operation Manual	Included	

## [Body Inspection]

<b>Upper Control</b>	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	Normal
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
<b>Lower Control</b>	Elevation/Extension/Rotation	Normal	Tool Box Corroded	
	Emergency pump	-	Upper Control LED Damaged	
	Emergency Stop	Normal	FRP Cover Damaged	
	Engine Start/Stop	Normal	Sub-Engine	



# No2010 Condition Check Sheet 2

Chassis Year	2011年	Emission Standard	BDG		
Chassis No.	XZU354-1002962	Model	SN15B	S/N	733416

## [Chassis Inspection]

Engine Oil Leak/Seepage	Oil Seepage	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Stained	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Fuel Seepage on Top of Engine	
Air Conditioner Operation/Performance	Normal	stained(Cabin)	
Pump	Normal		
Tire Tread Depth	Normal		

