

No2012 コンディションチェックシート①

車台番号	XZU600-0005891	点検日	2026/3/16
架装年式	2013年	経過年数	12年
機種	SN15B	号機	744361
走行距離	68,858km	アワメーター(トータル)	9,055h
アワメーター(メイン)	8,526h	アワメーター(サブ)	529h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

【架装部点検】


上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン(バッテリー)/ユニット	作動せず
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】 バッテリーユニットにて動作せず	
下部操作	起伏・伸縮・旋回	異常なし		
	非常用ポンプ	-		
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

株式会社 **アイチ** コーポレーション

No2012 コンディションチェックシート②

シャシ年式	2013年	排ガス記号	TKG
【車両部点検】	車台番号	XZU600-0005891	機種
			SN15B
	号機		744361
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	漏れ有	張出しシリンダ	異常なし
セルモーター異音・始動状態	漏れ有	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	オイル漏れ有
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	異常なし	首振モーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】 下部レベリングシリンダ油漏れ 異音(伸縮) バケットライナー割れ ラジエーター水漏れ有	
ミラー割れ・欠品	異常なし		
エアコン作動・能力	異常なし		
ポンプ	異常なし		
タイヤ山	タイヤ摩耗有		

株式会社 **アイチ** コーポレーション

No2012		Condition Check Sheet 1			
Chassis No.	XZU600-0005891			Inspection Date	16 Mar, 2026
Body Year	2013年			Service Age	12年
Model	SN15B	S/N	744361	Inspector	Y.T.
Mileage	68,858km		Hour Meter (Total)	9,055h	
Hour Meter (Main)	8,526h		Hour Meter (Sub)	529h	
Accessories	Included		Operation Manual	Included	
[Body Inspection]					
Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	Not Working	
	Winch Up/Down	Normal	Outrigger Slide	Normal	
	Emergency Stop	Normal	Jack Slide	Normal	
	Engine Start/Stop	Normal	[Remarks]		
Lower Control	Elevation/Extension/Rotation	Normal	Unable to Operate via Battery Unit		
	Emergency pump	-			
	Emergency Stop	Normal			
	Engine Start/Stop	Normal			
					
No2012		Condition Check Sheet 2			
Chassis Year	2013年			Emission Standard	TKG
Chassis No.	XZU600-0005891		Model	SN15B	S/N 744361
[Chassis Inspection]					
Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal		
Radiator Water Leak/Hose Damage	Leak	Outrigger Cylinder	Normal		
Starter Motor Noise/Starting Condition	Leak	Elevation Cylinder	Normal		
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal		
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Oil Leak		
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal		
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal		
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal		
Glass Crack/Scratch	Normal	[Remarks]			
Mirror Crack/Missing	Normal	Lower Leveling cylinder oil leak			
Air Conditioner Operation/Performance	Normal	Noise (Extension/Retraction)			
Pump	Normal	Bucket liner crack			
Tire Tread Depth	Tire Wear	Radiator Water Leak			
