



# No2015 Condition Check Sheet 1

Chassis No.	FE73DY-550283		Inspection Date	11 Mar, 2026	
Body Year	2009年		Service Age	17年	
Model	SH15B	S/N	727076	Inspector	Y.S.
Mileage	108,576km		Hour Meter (Total)	4,971h	
Hour Meter (Main)	4,971h		Hour Meter (Sub)	-	
Accessories	Included		Operation Manual	Not Included	

## [Body Inspection]

<b>Upper Control</b>	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	-
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
<b>Lower Control</b>	Elevation/Extension/Rotation	Normal	Jack marker lamp is out (4pc)	
	Emergency pump	Normal	FRP Cover Damaged	
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



# No2015 Condition Check Sheet 2

Chassis Year	2009年		Emission Standard	PDG		
Chassis No.	FE73DY-550283		Model	SH15B	S/N	727076

## [Chassis Inspection]

Engine Oil Leak/Seepage	Oil Seepage	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Oil Seepage	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Rust	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Engine Oil Seepage	
Air Conditioner Operation/Performance	Normal		
Pump	Normal		
Tire Tread Depth	Normal		

