

No2017 コンディションチェックシート①

車台番号	NKR85-7005498	点検日	2026/3/12
架装年式	2015年	経過年数	11年
機種	SH15B	号機	759649
走行距離	99,568km	点検者	K.O.
アワメーター(メイン)	13,039h	アワメーター(トータル)	14,752h
アワメーター(サブ)		アワメーター(サブ)	1,713h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/ バッテリー /ユニット	作動せず
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回	異常なし	バッテリーユニットにて動作できず サブブーム損傷	
	非常用ポンプ	-		
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

株式会社 アイチ コーポレーション

No2017 コンディションチェックシート②

シャ年式	2015年	排ガス記号	TKG
【車両部点検】	車台番号	NKR85-7005498	機種
			SH15B
	号機	759649	
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出しシリンダ	異常なし
セルモーター異音・始動状態	異常なし	起伏シリンダ	にじみ有
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デフアレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	破れ有	首振りモーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】 起伏シリンダオイルにじみ有 運転席破れ有	
ミラー割れ・欠品	異常なし		
エアコン作動・能力	異常なし		
ポンプ	異常なし		
タイヤ山	異常なし		

株式会社 アイチ コーポレーション

No2017		Condition Check Sheet 1			
Chassis No.		NKR85-7005498		Inspection Date	12 Mar, 2026
Body Year		2015年		Service Age	11年
Model	SH15B	S/N	759649	Inspector	K.O.
Mileage		99,568km	Hour Meter (Total)		14,752h
Hour Meter (Main)		13,039h	Hour Meter (Sub)		1,713h
Accessories		Included	Operation Manual		Included

[Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	Not Working
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Rotation	Normal	Unable to Operate via Battery Unit	
	Emergency pump	-	Sub-Boom Damaged	
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



No2017		Condition Check Sheet 2			
Chassis Year		2015年		Emission Standard	TKG
Chassis No.	NKR85-7005498	Model	SH15B	S/N	759649

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Seepage
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Torn	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Elevation Cylinder Oil Seepage	
Air Conditioner Operation/Performance	Normal	Torn (Driver Seat)	
Pump	Normal		
Tire Tread Depth	Normal		

