

コンディションチェックシート①

車台番号	XZU600-0012657	点検日	2026/2/28
架装年式	2016年	経過年数	10年
機種	SH15B	号機	767381
走行距離	1,290km	点検者	U.F.
アワメーター(メイン)	3,171h	アワメーター(サブ)	493h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/バッテリー/ユニット	異常なし
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回・首振り	異常なし	ジャッキ張幅MAX表示灯不灯(作動は正常)	
	非常用ポンプ	-	ジャッキマーカールンプ切れ(4カ所)	
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

株式会社 アイチ コーポレーション

コンディションチェックシート②

シャシ年式	2016年	排ガス記号	TKG
【車両部点検】	車台番号	XZU600-0012657	機種
			SH15B
			号機
			767381
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	異常なし
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	異常なし	首振モーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】	
ミラー割れ・欠品	異常なし	タイヤ摩耗有	
エアコン作動・能力	異常なし		
ポンプ	異常なし		
タイヤ山	タイヤ摩耗有		

株式会社 アイチ コーポレーション

Condition Check Sheet 1

Chassis No.	XZU600-0012657	Inspection Date	28 Feb, 2026
Body Year	2016年	Service Age	10年
Model	SH15B	S/N	767381
Mileage	1,290km	Hour Meter (Total)	3,664h
Hour Meter (Main)	3,171h	Hour Meter (Sub)	493h
Accessories	Included	Operation Manual	Included

[Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery Unit	Normal
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Jack width indicator light is off Max(Operation is normal) Jack marker lamp is out (4pc)	
	Emergency pump	-		
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



Condition Check Sheet 2

Chassis Year	2016年	Emission Standard	TKG
	Chassis No. XZU600-0012657	Model	SH15B
		S/N	767381

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks] Tire Wear	
Mirror Crack/Missing	Normal		
Air Conditioner Operation/Performance	Normal		
Pump	Normal		
Tire Tread Depth	Tire Wear		

