

コンディションチェックシート①

車台番号	NKR85-7007154	点検日	2026/2/28
架装年式	2008年	経過年数	17年
機種	SK10B	号機	721373
走行距離	176,429km	点検者	K.N.
アワメーター(メイン)	6,055h	アワメーター(トータル)	6,055h
アワメーター(サブ)		アワメーター(サブ)	-
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	なし

【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	ガタ有	バッテリーユニット	-
	ウインチ巻上・巻下	-	アウトリガスライド	-
	緊急停止	ガタ有	ジャッキスライド	-
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回・首振り	異常なし	上部緊急停止ボタン異常あり	
			バケット乗込みステップ変形	
	緊急停止	異常なし	輪止め損傷	
	エンジンスタート・ストップ	異常なし	非常用ポンプ作動せず	

株式会社 アイチ コーポレーション

コンディションチェックシート②

シャシ年式	2008年	排ガス記号	BKG
【車両部点検】	車台番号	NKR85-7007154	機種
			SK10B
			号機
			721373
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	-
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	錆有	上部バランスシリンダ	オイルにじみ有
シート破れ・汚れ	破れ有	首振モーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】	
ミラー割れ・欠品	ミラー損傷有	助手席破れ有	
エアコン作動・能力	異常なし	ミラー損傷有	
ポンプ	異常なし	タイヤ摩耗有	
タイヤ山	タイヤ摩耗有	エアコン吹出し口不良	

株式会社 アイチ コーポレーション

Condition Check Sheet 1

Chassis No.	NKR85-7007154	Inspection Date	28 Feb, 2026
Body Year	2008年	Service Age	17年
Model	SK10B	S/N	721373
Mileage	176,429km	Hour Meter (Total)	6,055h
Hour Meter (Main)	6,055h	Hour Meter (Sub)	-
Accessories	Included	Operation Manual	Not Included

[Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Has play	Battery Unit	-
	Winch Up/Down	-	Outrigger Slide	-
	Emergency Stop	Has play	Jack Slide	-
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Upper Emergency Stop Button Faulty	
			Bucket entry step deformation	
	Emergency Stop	Normal	Wheel Stopper Damaged	
	Engine Start/Stop	Normal	Emergency pump not working	



Condition Check Sheet 2

Chassis Year	2008年	Emission Standard	BKG
	Chassis No. NKR85-7007154	Model	SK10B
		S/N	721373

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	-
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Rust	Balance Cylinder (Upper)	Oil Seepage
Seat Tear/Stain	Torn	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Mirror damaged	Torn (Passenger Seat)	
Air Conditioner Operation/Performance	Normal	Mirror damaged	
Pump	Normal	Tire Wear	
Tire Tread Depth	Tire Wear	Air conditioner outlet defect	

