

コンディションチェックシート①

車台番号	XZU301-1002910	点検日	2026/2/20
架装年式	2006年	経過年数	19年
機種	SK10B	号機	697082
走行距離	110,888km	点検者	Y.T.
アワメーター(メイン)	7,417h	アワメーター(トータル)	7,417h
アワメーター(サブ)		アワメーター(サブ)	-
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン/バッテリー/ユニット	-
	ウインチ巻上・巻下	-	アウトリガスライド	-
	緊急停止	異常なし	ジャッキスライド	-
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回・首振り	異常なし	上部操作LED破損有	
	非常用ポンプ	異常なし	上部伸縮レバー固着有	
	緊急停止	異常なし	首振りエンド付近異音有	
	エンジンスタート・ストップ	異常なし	ブーム縮時ハンチングあり	

株式会社 **アイチ** コーポレーション

コンディションチェックシート②

シャシ年式	2006年	排ガス記号	PB
【車両部点検】	車台番号	XZU301-1002910	機種
			SK10B
		号機	697082
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	-
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	-
マフラ錆・変形	異常なし	上部バランスシリンダ	ダストシール損傷
シート破れ・汚れ	破れ有	首振モーター	異常なし
内張り破れ・汚れ	破れ有	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】	
ミラー割れ・欠品	異常なし	ダストシール損傷	
エアコン作動・能力	異常なし	シート破れ・汚れ有	
ポンプ	異常なし	タイヤ摩耗有	
タイヤ山	タイヤ摩耗有		

株式会社 **アイチ** コーポレーション

Condition Check Sheet 1

Chassis No.	XZU301-1002910	Inspection Date	20 Feb, 2026
Body Year	2006年	Service Age	19年
Model	SK10B	S/N	697082
Mileage	110,888km	Hour Meter (Total)	7,417h
Hour Meter (Main)	7,417h	Hour Meter (Sub)	-
Accessories	Included	Operation Manual	Included

[Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine/Battery/ Unit	-
	Winch Up/Down	-	Outrigger Slide	-
	Emergency Stop	Normal	Jack Slide	-
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Upper Control LED Damaged	
	Emergency pump	Normal	Upper Control Lever Seized (Extension/Retraction Lever)	
	Emergency Stop	Normal	Abnormal Noise Near Jib End	
	Engine Start/Stop	Normal	Self-induced Vibration During Retraction	



Condition Check Sheet 2

Chassis Year	2006年	Emission Standard	PB
	Chassis No. XZU301-1002910	Model	SK10B
		S/N	697082

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	-
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	-
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Dust Seal Damaged
Seat Tear/Stain	Torn	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Torn	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Dust Seal Damaged	
Air Conditioner Operation/Performance	Normal	Sheet Stained & Torn	
Pump	Normal	Tire Wear	
Tire Tread Depth	Tire Wear		

