

コンディションチェックシート①

車台番号	NKR85Y-7005548	点検日	2026/2/20
架装年式	2015年	経過年数	10年
機種	SN15B	号機	760127
走行距離	105,050km	点検者	Y.T.
アワメーター(メイン)	10,524h	アワメーター(サブ)	1,727h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異常なし	エンジン バッテリー / ユニット	作動せず
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回・首振り	異常なし	バッテリーユニットにて動作できず	
			ユニットバッテリー液不足	
	緊急停止	異常なし	上部ジョイスティックレバーイネーブルSWゴムブーツ損傷	
	エンジンスタート・ストップ	異常なし	工具箱ダンパーステー折損	
			輪止め欠品	

株式会社 アイチ コーポレーション

コンディションチェックシート②

シャシ年式	2015年	排ガス記号	TKG
【車両部点検】	車台番号	NKR85Y-7005548	機種
			SN15B
			号機
			760127
エンジンオイル漏れ・しみ	オイルにじみ有	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	異常なし
セルモーター異音・始動状態	異常なし	起伏シリンダ	オイル漏れ有
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	オイル漏れ有
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	破れ有	首振モーター	異常なし
内張り破れ・汚れ	破れ有	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】	
ミラー割れ・欠品	異常なし	エンジンオイルにじみ	
エアコン作動・能力	異常なし	起伏シリンダオイル漏れ	
ポンプ	異常なし	伸縮シリンダオイル漏れ	
タイヤ山	タイヤ摩耗有	タイヤ摩耗有	
		-	

株式会社 アイチ コーポレーション

Condition Check Sheet 1

Chassis No.	NKR85Y-7005548	Inspection Date	20 Feb, 2026
Body Year	2015年	Service Age	10年
Model	SN15B	S/N	760127
Mileage	105,050km	Hour Meter (Total)	12,251h
Hour Meter (Main)	10,524h	Hour Meter (Sub)	1,727h
Accessories	Included	Operation Manual	Included

[Body Inspection]

Upper Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Engine (Battery) Unit	Not Working
	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
Lower Control	Elevation/Extension/Retraction/Rotation/Swing	Normal	Unable to Operate via Battery Unit	
			Unit Battery Fluid Low	
	Emergency Stop	Normal	Upper Control Joystick Enable Switch Rubber Cover Damaged	
	Engine Start/Stop	Normal	Tool Box Damper Bracket Damaged	
			Wheel Stopper Missing	



Condition Check Sheet 2

Chassis Year	2015年	Emission Standard	TKG
	Chassis No. NKR85Y-7005548	Model	SN15B
		S/N	760127

[Chassis Inspection]

Engine Oil Leak/Seepage	Oil Seepage	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Oil Leak
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Oil Leak
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Torn	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Torn	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Engine Oil Seepage	
Air Conditioner Operation/Performance	Normal	Elevation Cylinder Oil Leak	
Pump	Normal	Extension Cylinder Oil Leak	
Tire Tread Depth	Tire Wear	Tire Wear	
		-	

