

## コンディションチェックシート①

車台番号	XZU600-0012745	点検日	2026/2/20
架装年式	2016年	経過年数	10年
機種	SH10A	号機	767673
走行距離	48,938km	点検者	M.K.
アワメーター(メイン)	2,614h	アワメーター(トータル)	2,614h
アワメーター(サブ)		アワメーター(サブ)	-
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

### 【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異常なし	バッテリーユニット	-
	ウインチ巻上・巻下	異常なし	アウトリガスライド	-
	緊急停止	異常なし	ジャッキスライド	-
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回・首振り	異常なし	異常なし	
	緊急停止	異常なし		
	エンジンスタート・ストップ	異常なし		

株式会社 **アイチ** コーポレーション

## コンディションチェックシート②

シャシ年式	2016年	排ガス記号	TKG
【車両部点検】	車台番号	XZU600-0012745	機種
			SH10A
			号機
			767673
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	-
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	異常なし	首振モーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】	
ミラー割れ・欠品	異常なし	異常なし	
エアコン作動・能力	異常なし		
ポンプ	異常なし		
タイヤ山	異常なし		

株式会社 **アイチ** コーポレーション

## Condition Check Sheet 1

Chassis No.	XZU600-0012745	Inspection Date	20 Feb, 2026
Body Year	2016年	Service Age	10年
Model	SH10A	S/N	767673
Mileage	48,938km	Hour Meter (Total)	2,614h
Hour Meter (Main)	2,614h	Hour Meter (Sub)	-
Accessories	Included	Operation Manual	Included

### [Body Inspection]

<b>Upper Control</b>	Elevation/Extension/Retraction/Rotation/Swing	Normal	Battery Unit	-
	Winch Up/Down	Normal	Outrigger Slide	-
	Emergency Stop	Normal	Jack Slide	-
	Engine Start/Stop	Normal	[Remarks]	
<b>Lower Control</b>	Elevation/Extension/Retraction/Rotation/Swing	Normal	Normal	
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



## Condition Check Sheet 2

Chassis Year	2016年	Emission Standard	TKG
	Chassis No. XZU600-0012745	Model	SH10A
		S/N	767673

### [Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	-
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Normal	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	Normal	Normal	
Air Conditioner Operation/Performance	Normal		
Pump	Normal		
Tire Tread Depth	Normal		

