

## コンディションチェックシート①

車台番号	NKR85Y-7005621	点検日	2026/2/26
架装年式	2015年	経過年数	11年
機種	SH15B	号機	761319
走行距離	121,034km	点検者	U.F.
アワメーター(メイン)	10,809h	アワメーター(サブ)	11,801h
アワメーター(メイン)	10,809h	アワメーター(サブ)	922h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

### 【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	異音(起伏)	エンジン(バッテリー) / ユニット	作動せず
	ウインチ巻上・巻下	異常なし	アウトリガスライド	錆有
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回・首振り	異音(起伏)	下部操作ボックスガスダンパー不良	
			ジャッキベース欠品(3枚)	
	緊急停止	異常なし	輪止め欠品(2個)	
	エンジンスタート・ストップ	異常なし	ブーム縮時ハンチングあり	
			異音(起伏)	

株式会社 アイチ コーポレーション

## コンディションチェックシート②

シャシ年式	2015年	排ガス記号	TKG
【車両部点検】	車台番号	NKR85Y-7005621	機種
			SH15B
			号機
			761319
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	異常なし
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デフレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	錆有	上部バランスシリンダ	異常なし
シート破れ・汚れ	破れ有	首振モーター	異常なし
内張り破れ・汚れ	汚れ有	旋回モーター	異常なし
ガラス割れ・傷	傷有	【備考欄】	
ミラー割れ・欠品	アンダーミラー欠品	バッテリーユニットにて動作できず	
エアコン作動・能力	異常なし	シート破れ・汚れ有	
ポンプ	異常なし	アンダーミラー欠品	
タイヤ山	異常なし	マフラ錆・変形	
			ライナープロテクタ割れ

株式会社 アイチ コーポレーション

# Condition Check Sheet 1

Chassis No.	NKR85Y-7005621	Inspection Date	26 Feb, 2026
Body Year	2015年	Service Age	11年
Model	SH15B	S/N	761319
Mileage	121,034km	Hour Meter (Total)	11,801h
Hour Meter (Main)	10,809h	Hour Meter (Sub)	922h
Accessories	Included	Operation Manual	Included

## [Body Inspection]

<b>Upper Control</b>	Elevation/Extension/ Retraction/Rotation/Swing	Noise (Elevation)	Engine <del>(Battery)</del> Unit	Not Working
	Winch Up/Down	Normal	Outrigger Slide	Rust
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks] Unable to Operate via Battery Unit Sheet Stained & Torn Under mirror missing Muffler Rust/Deformation Liner protector Cracked	
<b>Lower Control</b>	Elevation/Extension/ Retraction/Rotation/Swing	Noise (Elevation)		
	Emergency Stop	Normal		
	Engine Start/Stop	Normal		



# Condition Check Sheet 2

Chassis Year	2015年	Emission Standard	TKG
	Chassis No. NKR85Y-7005621	Model	SH15B
		S/N	761319

## [Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Rust	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Torn	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Stained	Rotation Motor	Normal
Glass Crack/Scratch	Scratch	[Remarks] Unable to Operate via Battery Unit Sheet Stained & Torn Under mirror missing Muffler Rust/Deformation Liner protector Cracked	
Mirror Crack/Missing	Under mirror missing		
Air Conditioner Operation/Performance	Normal		
Pump	Normal		
Tire Tread Depth	Normal		

