

## コンディションチェックシート①

車台番号	NKR85YN-7005216	点検日	2026/3/7
架装年式	2015年	経過年数	11年
機種	SH15B	号機	755743
走行距離	122,646km	点検者	S.S.
アワメーター(メイン)	11,351h	アワメーター(サブ)	1,148h
付属エアコン・スペアタイヤ・車載工具	あり	取扱説明書	あり

### 【架装部点検】

上部操作	起伏・伸縮・旋回・首振り	修理要	エンジン <del>バッテリー</del> / ユニット	作動せず
	ウインチ巻上・巻下	異常なし	アウトリガスライド	異常なし
	緊急停止	異常なし	ジャッキスライド	異常なし
	エンジンスタート・ストップ	異常なし	【備考欄】	
下部操作	起伏・伸縮・旋回・首振り	異常なし	上部停止LED点滅あり 修理要	
	非常用ポンプ	-	サブブーム検出リミットスイッチ欠品 修理要	
	緊急停止	異常なし	サブブーム欠品	
	エンジンスタート・ストップ	異常なし	バッテリーユニットにて動作できず	

株式会社 **アイチ** コーポレーション

## コンディションチェックシート②

シャシ年式	2015年	排ガス記号	SKG
<b>【車両部点検】</b>	車台番号	NKR85YN-7005216	機種
			SH15B
			号機
			755743
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ	異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出シリンダ	異常なし
セルモーター異音・始動状態	異常なし	起伏シリンダ	異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ	異常なし
デファレンシャルオイル漏れ・しみ	異常なし	下部バランスシリンダ	異常なし
マフラ錆・変形	異常なし	上部バランスシリンダ	異常なし
シート破れ・汚れ	破れ有	首振モーター	異常なし
内張り破れ・汚れ	異常なし	旋回モーター	異常なし
ガラス割れ・傷	異常なし	【備考欄】	
ミラー割れ・欠品	ミラー欠品	シート破れ・汚れ有	
エアコン作動・能力	異常なし	アンダーミラー欠品	
ポンプ	異常なし	助手席側パワーウィンドウ作動不良	
タイヤ山	異常なし	FRPカバー損傷	

株式会社 **アイチ** コーポレーション

# Condition Check Sheet 1

Chassis No.	NKR85YN-7005216	Inspection Date	07 Mar, 2026
Body Year	2015年	Service Age	11年
Model	SH15B	S/N	755743
Mileage	122,646km	Hour Meter (Total)	12,499h
Hour Meter (Main)	11,351h	Hour Meter (Sub)	1,148h
Accessories	Included	Operation Manual	Included

## [Body Inspection]

	Elevation/Extension/Retraction/Rotation/Swing	Repair Required	Engine/ <del>Battery</del> / Unit	Not Working
<b>Upper Control</b>	Winch Up/Down	Normal	Outrigger Slide	Normal
	Emergency Stop	Normal	Jack Slide	Normal
	Engine Start/Stop	Normal	[Remarks]	
	Elevation/Extension/Retraction/Rotation/Swing	Normal	Upper stop LED is flashing Repair Required	
<b>Lower Control</b>	Emergency pump	-	Sub-boom detection interlock switch missing Repair Required	
	Emergency Stop	Normal	Sub-Boom Missing	
	Engine Start/Stop	Normal	Unable to Operate via Battery Unit	



# Condition Check Sheet 2

Chassis Year	2015年	Emission Standard	SKG
	Chassis No. NKR85YN-7005216	Model	SH15B
		S/N	755743

## [Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Balance Cylinder (Lower)	Normal
Muffler Rust/Deformation	Normal	Balance Cylinder (Upper)	Normal
Seat Tear/Stain	Torn	Bucket Swing Motor	Normal
Interior Panel Tear/Stain	Normal	Rotation Motor	Normal
Glass Crack/Scratch	Normal	[Remarks]	
Mirror Crack/Missing	mirror missing	Sheet Stained & Torn	
Air Conditioner Operation/Performance	Normal	Under mirror missing	
Pump	Normal	Power window not working (Passenger Seat)	
Tire Tread Depth	Normal	FRP Cover Damaged	

