

コンディションチェックシート①

車台番号	FC9JGA-11460	点検日	2026/3/5	
架装年式	2016年	経過年数	9年	
機種	D70A	号機	768071	点検者
走行距離	99,115km	アワメーター(トータル)		4,230h
搭載品	ジャッキベース	4個	輪止め	4個
	スペアタイヤ	あり	車載工具	あり
取扱説明書				
あり				

【架装部点検】

作動確認	起伏・伸縮・旋回・首振り	異常なし	アタッチメント・ツール	異常なし
	ウインチ巻上・巻下	異常なし	ドライブシャフト	異常なし
	オーガ装置	異常なし	【備考欄】 ジャッキベース腐食有 操作席腐食有	
	過巻装置	異常なし		
	アウトリガ・ジャッキ	異常なし		
	エンジンスタート・ストップ	異常なし		
	作業灯	異常なし		
ホーン	異常なし			

株式会社 アイチ コーポレーション

コンディションチェックシート②

シャシ年式	2016年	排ガス記号	TKG	
【車両部点検】	車台番号	FC9JGA-11460	機種	D70A
			号機	768071
エンジンオイル漏れ・しみ	異常なし	ジャッキシリンダ		異常なし
ラジエーター水漏れ・ホース損傷	異常なし	張出しシリンダ		異常なし
セルモーター異音・始動状態	異常なし	起伏シリンダ		異常なし
ミッションオイル漏れ・しみ	異常なし	伸縮シリンダ		異常なし
デファレンシャルオイル漏れ・しみ	異常なし	オーガ減速機		異常なし
マフラ錆・変形	異常なし	旋回減速機		異常なし
シート破れ・汚れ	異常なし	ウインチ減速機		異常なし
内張り破れ・汚れ	異常なし	ウインチワイヤー		錆有
ガラス割れ・傷	異常なし	オーガー格納ワイヤー		錆有
ミラー割れ・欠品	異常なし	【備考欄】 PTOポンプシャフトシール油漏れ ウインチワイヤー錆有 オーガー格納ワイヤー錆有		
エアコン作動・能力	異常なし			
ポンプ	異常なし			
タイヤ山	異常なし			

株式会社 アイチ コーポレーション

Condition Check Sheet 1

Chassis No.	FC9JGA-11460	Inspection Date	05 Mar, 2026	
Body Year	2016年	Service Age	9年	
Model	D70A	S/N	768071	Inspector
Mileage	99,115km	Hour Meter (Total)	4,230h	
Accessories	Jack Bases	4pc	Wheel Stoppers	4pc
	Spare Tires	Included	On-board Tools	Included
Operation Manual Included				

[Body Inspection]

Control	Elevation/Extension/ Retraction/Rotation/Swing	Normal	Attachment/Tool	Normal
	Winch Up/Down	Normal	Drive Shaft	Normal
	Auger	Normal	[Remarks] Jack Base Corroded cockpit corrosion	
	Over-Hoist Limit Device	Normal		
	Outrigger/Jack	Normal		
	Engine Start/Stop	Normal		
	Work Light	Normal		
	Horn	Normal		



Condition Check Sheet 2

Chassis Year	2016年	Emission Standard	TKG	
	Chassis No. FC9JGA-11460	Model	D70A	S/N
				768071

[Chassis Inspection]

Engine Oil Leak/Seepage	Normal	Jack Cylinder	Normal
Radiator Water Leak/Hose Damage	Normal	Outrigger Cylinder	Normal
Starter Motor Noise/Starting Condition	Normal	Elevation Cylinder	Normal
Transmission Oil Leak/Seepage	Normal	Telescopic Cylinder	Normal
Differential Oil Leak/Seepage	Normal	Auger Reduction Gear	Normal
Muffler Rust/Deformation	Normal	Rotation Reduction Gear	Normal
Seat Tear/Stain	Normal	Winch Reduction Gear	Normal
Interior Panel Tear/Stain	Normal	Winch Wire	Rust
Glass Crack/Scratch	Normal	Auger Stowage Wire	Rust
Mirror Crack/Missing	Normal	[Remarks] PTO pump shaft seal oil leak Winch Wire Rust Auger Stowage Wire Rust	
Air Conditioner Operation/Performance	Normal		
Pump	Normal		
Tire Tread Depth	Normal		

